

VISIBLE EMISSION NOTATIONS				
Inspector: Jaime N GORO	<u> 1</u>			
Date of Inspection: 10///15				
Shift: 1st Shift or 2nd Shift	Time:	5ph	Comments	
Unit	Visual Inspection <u>NORMAL</u> or ABNORMAL		COMMENTS	
Visible Emission From Shaker	Non			
Visible Emission From Discharge Conveyor System	Non	e processor de la companya de la com		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







VISIBLE EMISSION NOTATIONS			7	
Inspector:	land III			
Date of Inspection:	2015		_	
Shift: 1st Shift or 2nd Shif	Time:	5:00am		The state of the s
the and the Unit School points of the Control of th	Visual Inspection (4)			
	NORMAL or ABNORMAL			
Visible Emission From Shaker	Normal			
Visible Emission From Discharge				
Conveyor System	N yrmal			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS			7		
Inspector: 1000 MO	tendu				
Date of Inspection:					
Shift: 1st Shift or 2nd Shift	Time:	5:00 am			Symposium and a second
Unit	Visual Inspection NORMAL			nments	
	or <u>ABNORMAL</u>	The second secon	The second secon		
Visible Emission From Shaker	Normal				
Visible Emission From Discharge	Novmal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS Inspector: Date of Inspection: Time: 2nd Shift Shift: Comments Visual Unit Inspection NORMAL or **ABNORMAL** Visible Emission From Shaker Visible Emission From Discharge Conveyor System

Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.

Cause the greatest emissions.
 Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.





VISIBLE EMISSION NOTATIONS			1		
Inspector:	Molenelin				
Date of Inspection: 16 3 3	615				
Shift: 1st Shift 2nd Shift	Time:	5:00 am		THE RESIDENCE OF THE PROPERTY	
	Visual Inspection NORMAL	Constitution of the second seco	Go	mments	
	or L <u>ABNORMAL</u>				
Visible Emission From Shaker	Normal				
Visible Emission From Discharge	n hymal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.








VISIBLE EMISSION NOTATIONS			7		
Inspector: George A. Souche	,e				
Date of Inspection: 0/8/15	-				
Shift: 1st Shift or 2nd Shift	Time:	5:00 pm			The second section is a second
	Visual Inspection:		COI	nments:	
	Or ABNORMAL				
Visible Emission From Shaker	Nor				
Visible Emission From Discharge	Mar				
Conveyor System	100	1 -			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







VISIBLE EMISSION NOTATIONS

VISIBLE EMISSION NOTATIONS			7			
Inspector: Smc 1k0						
Date of Inspection: Oct 4,15						
Shift: 1st Shift or 2nd Shift	Time: 4	5AM		CONTROL OF THE PROPERTY OF THE	enteronicoloriste provincia de la	rancamente es mai supresentat de establica
fersystem per als Uniteración etallos es s as reconstructos estados estados estados	Visual IIII			Comments :		
	<u>NORMAL</u>		pper production of the surface of th	i e de la companion de la comp La companion de la companion de		
	or <u>ABNORMAL</u>					
Visible Emission From Shaker	NOR	1				
Visible Emission From Discharge	NOV					
Conveyor System	NUN					


- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS			7		
Inspector: Crange A South Date of Inspection: 15/4/15	/ C				
0/4/10	·- ·- ·- ·- ·- ·- ·- ·- ·- ·- ·- ·- ·- ·		_		
Shift: 1st Shift or 2nd Shift	Time:	5:60pm			
	Visual Inspection				
	<u>NORMAL</u> 3				
	<u>ABNORMAL</u>			用 指制度。新原尼等377年新州的	· · · · · · · · · · · · · · · · · · ·
Visible Emission From Shaker	Wor		-		
Visible Emission From Discharge Conveyor System	Wor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to
 cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.





VISIBLE EMISSION NOTATIONS	
Inspector: Sme VO	
Date of Inspection: 0 + 5 (T	

The same of the sa		11.	L		
And Documents On the Angle of the Control of the Co	re when Visual is the		Commer	ntsa: ma come	
	inspections.		e and market and a second of the second of t		
	<u>NORMAL</u>	Liver Backgroup in			
	ABNORMAL				
Visible Emission From Shaker	nop	, which is a second of the sec			
Visible Emission From Discharge	000				
Conveyor System	1101				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







VISIBLE EMISSION NOTATIONS			 7		
Inspector: Jaime N Gar	cia				
Date of Inspection: 10/5/15					
Shift: 1st Shift or 2nd Shift	Time:	5pm			
Linit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>			Comments	
Visible Emission From Shaker	Non	- Comments			
Visible Emission From Discharge Conveyor System	Non				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







VISIBLE EMISSION NOTATIONS			-			
Inspector: Mc	land III					
Date of Inspection: 10-6-3	WIS	500am			·	
Shift: 1st Shift or 2nd Shift	Time:					- 1. AT 10.17
Adam and the Control of the Control	Visual		COM - Proposition of the Table - Proposition of the Table	iments () () () () () () () () () (
	NORMAL Of				es endre grant en met en La companya de la co	
	<u>ABNORMAL</u>					
Visible Emission From Shaker	Normal					
Visible Emission From Discharge	Normal					

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







VISIBLE EMISSION NOTATIONS			٦		
Inspector: Jaime N Gar	<u> </u>				
Date of Inspection: 10/6/15					
Shift: 1st Shift or 2nd Shift	Time: a	5 pm	the second single-posterior	THE RESERVE THE PROPERTY IN TH	Trollegum (Sandardan San Marka Sandartan)
de acompositiones (Unitable) de la compositione de	Visual William III		Comn	La de la companya de	
	NORMAL L OG				
。 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	<u>ABNORMAL</u>				
Visible Emission From Shaker	Non				A-8700
Visible Emission From Discharge	A/				
Conveyor System	Nor	- Control of the Cont			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



AIZIRFE FINISZION MOTATIONS			7		
Inspector: Ruber	- Molara	Qui			
Date of Inspection:	15				
Shift: 1st Shift or 2nd Shift	Time:	5:00am			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>			mments	
Visible Emission From Shaker	Normal				
Visible Emission From Discharge Conveyor System	Normal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS						
Inspector:	Sweets_					
Date of Inspection:						
10-7-15						
Shift: 1st Shift or 2nd Shift	Time:	600pm				
Unit	Visual	V	and the second s	omments -		er er er er
anathragen in 1975 Physics College	Inspection	100		The second secon	and the second s	
A Management of the Control of Principles (1997) and the Control of Principles (1997)	<u>NORMAL</u>			$(-1)^{-1} \left(\frac{1}{2} \right) $		
	or					
	ABNORMAL					10.1
Visible Emission From Shaker	Abrosmal	66.00	boot leaking	1. " / Use	duct tape	
	MOI Ma	- Ovarez	Vac letting	/ / - · · · · · · · · · · · · · · · · · 		
Visible Emission From Discharge			•	J		
Conveyor System	NO Rmer					

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to
 cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







VISIBLE EMISSION NOTATIONS					
Inspector: Smello					
Date of Inspection:	5				
Shift: 1st Shift or 2nd Shift	Time:) HVV I		and the second s	erromineur ander en och en en en en
	Visual Visual III	programing the control of the contro	The state of the s	mments (* 1866) 1908 - British Marie (* 1866) 5 January (* 1866)	
	NORIVAL				
	ABNORMAL				经过4英以外的 的图象是1200年第1200年8
Visible Emission From Shaker	noß	9			
Visible Emission From Discharge	0002	_			
Conveyor System	1.30				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.





VISIBLE EMISSION NOTATIONS			7			
Inspector: George A Sand	hr					
10/8/13						
Shift: 1st Shift or 2nd Shift	Time:	5:00 pm		aartska annamista kastiin ja		
	大学 Apple Visual Table (中央	SALE TO BE A TANK AND A SALE OF THE PARTY OF	e distribuit de la company de la company La company de la company d	mmenuse		
	<u>NORMAL</u>					
	or <u>ABNORMAL</u>					
Visible Emission From Shaker	Non					
Visible Emission From Discharge	Nor					
Conveyor System	1001				<u> </u>	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS,			1		
Inspector: Paul La	<u>Y</u>				
Date of Inspection:					
Shift: 1st Shift or 2nd Shift	Time:	5:00 AN			
Maria de la companya	/ Visual Visual Island		CONTRACTOR	nments = 100 mg	
	NORMAL		Andreas Commence of the Commen		
	ABNORMAL				
Visible Emission From Shaker	100				
Visible Emission From Discharge	Ner				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







VISIBLE EMISSION NOTATIONS			_			
Inspector:						
CHOISE NOR	/re =					
Date of Inspection:				•		
10/9/13	-		4			
Shift: (1st Shift) or 2nd Shift	t Time:	1260 m				
	Тоже при ожнопримерой обиданного достатура и податура	Terretain commence de la commence de		Description of the same of the same state of the same	THE PARTY WAS A PROPERTY OF THE PARTY OF THE	en erringen den
tutti etti ja	A Service Visual Tale Service	Particular Committee		omments - 15		
	Inspection 1-4	apparent aggregation and and the	one) on the parameter of the parameter	and the second s	era de partir de la compa	
	<u>NORMAL</u>					
	er sonatu					
	ABNORMAL					
Visible Emission From Shaker	41					
	Nor		•			
Visible Emission From Discharge	1)					
Conveyor System	NON					

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.








VISIBLE EMISSION NOTATIONS					
Inspector: Smelko					
Date of Inspection:	()				
Shift: 1st Shift or 2nd Shift	Time:	5 PM			
The state of the s	Visual did		en e	(A) 1000 (1000 (TEST)	
	NORMAL FOR				
	<u>ABNORMAL</u>	10 miles 100 miles			
Visible Emission From Shaker	nof	all designation as a second se			
Visible Emission From Discharge	nor				


- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.





VISIBLE EMISSION NOTATIONS			7		
Inspector: M. DHILLIPS			_		
Date of Inspection:	-	· · · · · · · · · · · · · · · · · · ·			
Shift: 1st Shift or 2nd Shift	Time:	5:00 pm.	the state of the s		
The action of the Unit Head of the Section of the S	Visual Linspection			mments and the second s	
	NORMAL OF ABNORMAL				
Visible Emission From Shaker	MRMAL				
Visible Emission From Discharge					
Conveyor System	NOGMAL	-			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS Inspector: Carria Date of Inspection: Time: 5 2nd Shift Shift: Comments Visual Unit Inspection NORMAL or <u>ABNORMAL</u> Visible Emission From Shaker Visible Emission From Discharge Conveyor System

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Inspector: Coope A June 15	el				
Shift: (1st Shift) or 2nd Shift	Time:	5:00 pm	(n)	nments	
. Unit	Visual Inspection NORMAL				
	or ABNORMAL 2				
Visible Emission From Shaker Visible Emission From Discharge Conveyor System	Nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

VISIBLE EMISSION NOTATIONS				in the second se	
Inspector: George Asi	neker				
Date of Inspection:	•				
Shift: 1st Shift or 2nd Shift	t Time: (5:00pm		The same of the sa	
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments		13 (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)
Visible Emission From Shaker	Nor				A Second
Visible Emission From Discharge Conveyor System	Nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Conveyor System

VISIBLE	EMISSION	NOTATIONS
----------------	-----------------	-----------

*				
Inspector: Smello				
Date of Inspection: 0e+14	,15			
Shift: 1st Shift or 2nd Shift	t Time:	SAM		
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments'	
Visible Emission From Shaker	nor			
Visible Emission From Discharge Conveyor System	nop			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

	_						
VISIBL	\vdash	1- N/i	155	ION.	NO.	ΙΔΙ	1ONS

Inspector: George A San	rchez	100° 110° 120° 110° 110° 110° 110° 110°		
Date of Inspection: 10/14/15				
Shift: 1st Shift or 2nd Shif	t Time:	5:00 pm		
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Non			
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.








VISIBLE EMISSION NOTATIONS

VISIBLE LIVISSION NOTATIONS			_	
Inspector: LINGO 11	CUANDIA			
Date of Inspection:)6			
Shift: 1st Shift or 2nd Shift	ft Time:	500AM		
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	NORMAL			
Visible Emission From Discharge Conveyor System	Normal			


- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS

Inspector:				
Date of Inspection:		 -		
Shift: 1st Shift or 2nd Shif	t Time:			
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Dum			-
Visible Emission From Discharge Conveyor System	Soro			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.




VISIBLE EMISSION NOTATIONS				
Inspector:				
M. PHILL	195			
Date of Inspection:	•			
10-16-1	<u> </u>			
Shift: 1st Shift or 2nd Shift				
155 SHIFT		5:00 PM.		
	Visual Inspection <u>NORMAL</u> or ABNORMAL		Comments	
Visible Emission From Shaker	NURMAL			·
Visible Emission From Discharge				
Conveyor System	NORMAL			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

AISIBLE EMISSION MOTATIONS			•	
Inspector:	en Moder	d		
Date of Inspection:)-15			
Shift: 1st Shift or 2nd Shif	Time:	B:Ca		
SUNIT Products Constitution of the Constitutio	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Norm			
Visible Emission From Discharge Conveyor System	Now			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.




VISIBLE EMISSION NOTATIONS				
Inspector: Prome & Sans	where			
Date of Inspection: 16/17/15				
Shift: 1st Shift or 2nd Shift	t Time:	(100 pm		7.7.7.4 (41)
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Nor			
Visible Emission From Discharge Conveyor System	Nas			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS					
Inspector:	L				
Date of Inspection:					
Shift: 1st Shift or 2nd Shift	Time:	5.00 AM			
See 2 Unit or	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Com State of the control of the con	ments	
Visible Emission From Shaker	Nov				
Visible Emission From Discharge Conveyor System	nor				


- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.





VISIBLE EMISSION NOTATIONS			7		
Inspector: Chema	S.	:			
Date of Inspection:	5				
Shift: Lst Shift or 2nd Shift	Time:	530pm			
Unit and the second sec	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comme	nts	
Visible Emission From Shaker	Abn.	shaker be	oot needs chan	yiny	
Visible Emission From Discharge	NOB.			U J	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS Inspector: Date of Inspection: Shift: 1st Shift or 2nd Shift Time: Unit Visual Comments Inspection NORMAL or ABNORMAL Visible Emission From Shaker

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Visible Emission From Discharge

Conveyor System



VISIBLE EMISSION NOTATIONS						
Inspector: Saime N Garan	iq					
Date of Inspection:	-					
Shift: 1st Shift or 2nd Shift	Time:	5 pm	The company of the last to the last the last to the la	are in Cherical Colors of the	en e	
SHOULD BE SEEN LOOK OF SUIT THE SAME OF SUIT SUIT SUIT SUIT SUIT SUIT SUIT SUIT	Visual Inspection 15.			:Gomments		
	<u>NORMAL</u> IOI ABNORMAL					
Visible Emission From Shaker	NORMA!		·			
Visible Emission From Discharge Conveyor System	Noemal					La Liver Control of the Control of t


- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE ENHISSION NOTATIONS			_		
Inspector: Hunn	loland				
Date of Inspection:	0-15				
Shift: 1st Shift or 2nd Shift	Time:	***************************************			
Unit	Visual		Comme	ents.	
 A supplier of the property of the	Inspection	e en continue en la companya de la companya del companya del companya de la compa			
	<u>NORMAL</u>	Arest engages and a second			
The second state of the se	or the state of th	The state of the s			
	<u>ABNORMAL</u>				
Visible Emission From Shaker	Noin				
Visible Emission From Discharge	1 600				
Conveyor System	VO142				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

AIZIBLE EMISSION NOTATIONS				
Inspector: Dime N GORC				
Date of Inspection: 10/20/15				
Shift: Lest Shift or 2nd Shift	: Time:	5 pm		
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments State of the state of	
Visible Emission From Shaker	Normal			
Visible Emission From Discharge Conveyor System	Morma (

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS

Inspector:

Date of Inspection:

Shift: 1st Shift or 2nd Shift Time: 5.00000

Agrana .	in-				
Unit	Visual		Comm	ents	
	Inspection	and the second s		10 (1996) 10 (1996)	
	<u>NORMAL</u>	And the second second second		100 mg 1 m	en e
	or				PARTITION OF THE PROPERTY OF THE PARTY OF TH
THE STATE OF THE S	<u>ABNORMAL</u>		and the state of t		
Visible Emission From Shaker	Nomal				
Visible Emission From Discharge	1000				
Conveyor System	1 WINGE				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			_		
Inspector: George A James	hez			•	
Date of Inspection:					
Shift: 2st Shift or 2nd Shift	Time:	5.00pm			
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>			Comments	
Visible Emission From Shaker	Nor				-
Visible Emission From Discharge Conveyor System	Nor				


- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			_		
Inspector: Seferny Har	Lin				
Date of Inspection:	7				
Shift: 1st Shift or 2nd Shift	Time:	500am			
, Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Col	mments	
Visible Emission From Shaker	wormal				
Visible Emission From Discharge Conveyor System	Normal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS				
Inspector: Chare A Sura	hoz			
Date of Inspection: 16/24/15	Reso			
Shift: Ast Shift or 2nd Shift	t Time:	5:00,000		
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments Comments Comments	
Visible Emission From Shaker	Wor			
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



AIZIRLE EV	/IISSION	INOI	AHONS	
Inspector:		1	1.2	

Date of Inspection:

Shift: 1st Shift or 2nd Shift

Time:

Maria Caracteria Carac		2 - 00 11110			
Francisco de la companya del companya de la companya del companya de la companya	Visual Inspection <u>NORMAL</u> or		Comn	nents	
Visible Emission From Shaker	<u>ABNORMAL</u>				
Visible Emission From Discharge Conveyor System	Nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS						
Inspector: Gare A Son	neker					
Date of Inspection:	115					
Shift: 1st Shift or 2nd Shift	Time:	S500pm		5 C C T T T T T T T T T T T T T T T T T	en en en el en en el en en el en	
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>			Comments		
Visible Emission From Shaker	Na					
Visible Emission From Discharge Conveyor System	Nor					

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS			~7			
Inspector: Well all			_		•	
Date of Inspection:	5					
Shift: 1st Shift or 2nd Shift	Time:	5100 M				
	Visual Inspection NORMAL			Comments		
	or <u>ABNORMAL</u>			The second secon		
Visible Emission From Shaker	Nor					
Visible Emission From Discharge	NOT					

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Quality is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS						
Inspector: Jaime Al Gar	?c/a				•	
Date of Inspection: 10/24/15			_			
Shift: 1st Shift or 2nd Shift	Time:	JAM				
Unit	Visual			Comments	er en	en en state per en en della en en el el en en el e El en en el en
	Inspection	Company of the Compan			British Co.	THE STATE OF STATE OF
	<u>NORMAL</u>					
and the third hadron of Files and Article	or such	100 May 200 Ma				
A STATE OF THE PARTY OF THE STATE OF THE STA	<u>ABNORMAL</u>				Not the second of the second o	
Visible Emission From Shaker	MORMAL					
Visible Emission From Discharge	A C					
Canyovar System	Mormal	1				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS			1		
Inspector:	Idany_				
Date of Inspection:	10-25-1	3			
Shift: 1st Shift or 2nd Shift	Time:	5.ccam_			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>			ments	
Visible Emission From Shaker	Norm				
Visible Emission From Discharge Conveyor System	Nom				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.








VISIBLE EMISSION NOTATIONS						
Inspector:	PHILLIPS				•	
Date of Inspection:	0HILLIPS 25-15					
Shift: 1st Shift or 2nd Shift		pm.				
Unit	Visual Inspection <u>NORMAL</u>			Comments		
	or <u>ABNORMAL</u>					Secure Security (1997)
Visible Emission From Shaker	NORM.					
Visible Emission From Discharge Conveyor System	NORM.					

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS			7		
Inspector:					
Date of Inspection:					
Shift: 1st Shift or 2nd Shif	Time:			avytes in well-stated Harkett Harkett in State of State o	
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>	Programme and the control of the con			
Visible Emission From Shaker	Normal				
Visible Emission From Discharge	Normal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.


VISIBLE EMISSION NOTATIONS			_			
Inspector: George Asa	nekez				•	
Date of Inspection: 10/26/15		- Control of the Cont				
Shift: 1st Shift or 2nd Shift	Time:	5:00 pm	2000年,1970年,1970年,1970年,1970年,1970年,1970年,1970年		ann an	
Unit	Visual			Comments		
er eine Broggerie (j. 1916) die 1912 Allen Wille (j. 1916) 1913 - De de Broggerie (j. 1916) die 1913 - De	Inspection			apt Cartina and Ca	1967 11 55	
	<u>NORMAL</u>					
	or	1874 - F				particular to the
	<u>ABNORMAL</u>		energy of the second se			
Visible Emission From Shaker	Nor					
Visible Emission From Discharge	41					
Canyayar System	War					

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Cause the greatest emissions.
 Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS			٦		
Inspector: Smello			_		
Date of Inspection:	5		_		
Shift: 1st Shift or 2nd Shift	Time: ,	5A.			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>			omments.	
Visible Emission From Shaker	noR				
Visible Emission From Discharge Conveyor System	noR				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to
 cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS	
Inspector: George Alunchez	
Date of Inspection: 18/24/15	
Shift: Act Shift or 2nd Shift	Time: 0 - 013

		3 00	I	115-715-1-31-32-84-014-95-4-3182-5	400	
Unit	Visual		-Com	iments	and the state of t	
 And Andrews (September 1997) and the September 1997 and	Inspection				Maria de Carlos de C Carlos de Carlos de Carlo	de la companya da di salah da
The second of th	<u>NORMAL</u>					
A Trade of the control of the contro	or +					ALLEGE OF THE STATE OF
	<u>ABNORMAL</u>	19 No. 19	er de la companya de			
Visible Emission From Shaker	Nor					
	ļ					
Visible Emission From Discharge	12					
Conveyor System	Nor					

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to
 cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.




VISIBLE EMISSION NOTATIONS			¬		
Inspector: Smell6					
Date of Inspection: Oct AS	5				
Shift: 1st Shift or 2nd Shift	Time: _	AM			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>			ments	
Visible Emission From Shaker	NOF				
Visible Emission From Discharge Conveyor System	noR				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS					
Inspector: IM . PIJ15	LIPS				
Date of Inspection:	8-15				
Shift: 1st Shift or 2nd Shift	Time:	5 pm	and the survey survey survey and the survey		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>			Comments	
Visible Emission From Shaker	NORMAL	. New State			
Visible Emission From Discharge Conveyor System	NORMAZ	And the second second			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.




VISIBLE EMISSION NOTATIONS			٦			
Inspector:					·	
Date of Inspection:						
Shift: 1st Shift or 2nd Shif	t Time:	·				
Unit Visible Emission From Shaker	Visual Inspection <u>NORMAL</u> Or <u>ABNORMAL</u>			Comments	The second secon	
Visible Emission From Discharge	u \					

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Conveyor System

VISIBLE EMISSION NOTATIONS						
	201a		_		·	
Date of Inspection: 0/19/18		_				
Shift: 1st Shift for 2nd Shift	Time:	Ph	······································			
	Visual Inspection <u>NORMAL</u> or			Comments.		
Visible Emission From Shaker	ABNORMAL NOEmal					Service Control of the Control of th
Visible Emission From Discharge Conveyor System	Norma (

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS			7		
Inspector: Name N Calle	aya		-		
Date of Inspection: 10/30/15		A Company of the Comp	-		
Shift: 1st Shift or 2nd Shift	Time: 2	ppin		nments	
- Unit	Visual Inspection <u>NORMAL</u>				
Visible Emission From Shaker	or ABNORMAL				
Visible Emission From Discharge	Wolfrer				
Conveyor System	Normal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.





VISIBLE EMISSION NOTATIONS			¬		
Inspector:	Uta, V		1		
Date of Inspection:					
Shift: 1st Shift or 2nd Shift	Time:				
	Visual Inspection <u>NORMAL</u> or ABNORMAL			Comments	
Visible Emission From Shaker	Abramal	Change So	erlen		
Visible Emission From Discharge Conveyor System	normal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Cause the greatest emissions.
 Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS				
Inspector: heave A Sunch	ke			
Date of Inspection: 10/31/15				
Shift: 1st Shift of 2nd Shift	Time:	5:00 pm		
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Non			
Visible Emission From Discharge	Nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.